

AFCTN Test Report 94-076

AFCTB-ID 94-027



Technical Publication Transfer Using:



Texas Instruments' Data Supporting:



U.S. Army Missile Command's TOW ITAS Program

(Contract #DAAH01-93-C-0206)



MIL-STD-1840A MIL-M-28001A (SGML) MIL-D-28003 (CGM)

Quick Short Test Report

Approved for public released

Distribution Unlimited

18 April 1994

19960822 118



Prepared for Electronic Systems Center Air Force CALS Program Office HQ ESC/AV-2 4027 Colonel Glenn Hwy Suite 300 Dayton OH 45431-1672

DTIC QUALITY INSPECTED 3

Technical Publication Transfer Using:
Texas Instruments' Data Supporting:
U. S. Army Missile Command's TOW ITAS Program
(Contract #DAAH01-93-C-0206)

MIL-STD-1840A MIL-M-28001A (SGML) MIL-D-28003 (CGM)

Quick Short Test Report 18 April 1994

Prepared By

Air Force CALS Test Bed Wright-Patterson AFB, OH 45433

AFCTB Contact

Gary Lammers (513) 427-2295

AFCTN Contact

Mel Lammers (513) 427-2295 DITC QUALITY INSPECTED 3

DISCLAIMER

This document was prepared as an account of the work sponsored by the Air Force. Neither the United States Government, the Air Force, nor any of their employees makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, nor represents that its use would not infringe on privately owned rights. Reference herein to any specific commercial products, process, or service by trade name, trademark, manufacturer, or otherwise, does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or the Air Force. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or the Air Force, and shall not be used for advertising or product endorsement purposes.

Available to the public from the National Technical Information Service U.S. Department of Commerce 5285 Port Royal Road Springfield, VA 22161

This report and those involved in its preparation do not endorse any product, process, or company stated herein. Use of these means by anyone does not imply certification by the Air Force CALS Test Network (AFCTN).

Air Force CALS Test Bed

Notification of Test Results

18 April 1994

This notice documents the results of an Air Force CALS Test Bed (AFCTB) Quick Short Test Report (QSTR) evaluation of data submitted by:

Texas Instruments

Identified as follows:

Title:

Technical Publication Transfer

Program:

TOW ITAS

Program Office:

U. S. Army Missile Command

Contract No.:

DAAH01-93-C-0206

OSTR No.:

AFCTB-ID 94-026

Received on the following media:

9-Track Tape

The results of the OSTR evaluation are as follows:

MIL-STD-1804A Standard

Fail

MIL-STD-1840A Media Format:

Fail

MIL-D-28000A IGES:

N/A

MIL-M-28001A SGML: MIL-R-28002A Raster:

Fail N/A

MIL-D-28003 CGM:

Fail

Formal results with associated disclaimer are documented and available from the AFCTB.

> Air Force CALS Test Bed HO ESC/AV-2P 4027 Colonel Glenn Highway, Suite 300 Dayton, OH 45431-1672

Phone: 513-257-3085

FAX: 513-257-5881

Contents

1.	Introduction1						
	1.1.	Background1					
	1.2.	Purpose2					
2.	Test 1	arameters3					
3.	1840A	Analysis6					
	3.1.	External Packaging6					
	3.2.	Transmission Envelope6					
		3.2.1. Tape Formats6					
		3.2.2. Declaration and Header Fields7					
4.	IGES A	nalysis8					
5.	SGML Analysis8						
6.	Raste:	Analysis9					
7.	CGM Analysis9						
8.	Conclusions and Recommendations12						
9.	Appen	lix A - Tapetool Report Logs13					
	9.1.	Tape Catalog13					
	9.2.	Tape Evaluation Log14					
	9.3.	Tape File Set Validation Log15					
	9.4.	Other Tape Reading Logs21					
10.	Appen	lix B - Detailed SGML Analysis23					
	10.1.	Parser Log23					
	10.2.	Exotercia Validator25					

	10.3.	Exoterica	XGMLNo	rmalizer E	arser	25
	10.4.	Sema Mark	:-it Log			25
11.	Append	lix C - De	tailed (CGM Analys	sis	26
	11.1.	File D001	.C004			26
		11.1.1.	Parser 1	Log MetaCh	neck	26
		11.1.2.	validcg	n Log		27
		11.1.3.	Output (CADLeaf		29
		11.1.4.	Output o	cgm2draw/]	slandDraw	30
		11.1.5.	Output I	Designer.		31
		11.1.6.	Output 1	Freelance.		32
		11.1.7.	Output 1	Harvard Gi	caphics	33
		11.1.8.	Output 3	IslandDrav	v v4.0	34
		11.1.9.	Output '	Ventura Pu	ablisher	35
		11.1.10.	Output 3	X-Change.		36
	11.2.	File D001	LC020	• • • • • • • •		37
		11.2.1.	Parser	Log MetaCl	neck	37
		11.2.2.	validcg	m Log		38
		11.2.3.	Output	CADLeaf		40
		11.2.4.	Output	cgm2draw/	IslandDraw	41
		11.2.5.	Output :	Designer.		42
		11.2.6.	Output	Freelance		43
		11.2.7.	Output	Harvard G	raphics	44
		11.2.8.	Output	IslandDra	w v4.0	45
		11.2.9.	Output	X-Change.		46

	11.2.10.	Output	Ventura	Publisher.			4	7
11.3.	File D00	2C001					4	8
	11.3.1.	Parser	Log Meta	aCheck			4	8
	11.3.2.	validc	gm Log				5	0
	11.3.3.	Output	CADLeaf				5	2
	11.3.4.	Output	cgm2dra	w/IslandDra	w		5	3
	11.3.5.	Output	Designe	r			5	4
	11.3.6.	Output	Freeland	ce		. 	5	5
	11.3.7.	Output	Harvard	Graphics			5	6
	11.3.8.	Output	IslandD:	raw v4.0			5	7
	11.3.9.	Output	X-Change	e			5	8

1. Introduction

1.1 Background

The Department of Defense (DoD) Air Force Continuous Acquisition and Life-cycle Support (CALS) Test Network (AFCTN) is conducting tests of the military standard for the Automated Interchange of Technical Information, MIL-STD-1840A, and its companion suite of military specifications. The AFCTN is a DoD sponsored confederation of voluntary participants from industry and government managed by the Electronic Systems Center (ESC).

The primary objective of the AFCTN is to evaluate the effectiveness of the CALS standards for technical data interchange and to demonstrate the technical capabilities and operational suitability of those standards. Two general categories of tests are performed to evaluate the standards; formal and informal.

Formal tests are large and comprehensive, which follow a written test plan, require specific authorization from the DoD, and may take months to prepare, execute, and report.

Informal tests are quick and short, used by the AFCTN technical staff, to broaden the testing base. They include representative samples of the many systems and applications used by AFCTN participants. They also allow the AFCTN staff to gain feedback from many industry and government interpretations of the standards, to increase the base of participation in the CALS initiative, and respond to the many requests for help that come from participants. ticipants take part voluntarily, benefit by receiving an evaluation of their latest implementation (interpretation) of the standards, interact with the AFCTN technical staff, gain experience using the standards, and develop increased confidence in them. The results of informal tests are reported in Quick Short Test Reports (QSTRs) that briefly summarize the standard(s) tested, the hardware and software used, the nature of the test, and the results.

1.2 Purpose

The purpose of the informal test, reported in this QSTR, was to analyze Texas Instrument's interpretation and use of the CALS standards in transferring technical publication data. Texas Instruments used its CALS Technical Data Interchange System to produce data, in accordance with the standards, and delivered it to the AFCTN technical staff on a 9-track magnetic tape.

2. Test Parameters

Test Plan:

AFCTB 94-027

Date of

Evaluation:

18 April 1994

Evaluator:

George Elwood

Air Force CALS Test Bed

DET 2 HQ ESC/AV-2P 4027 Colonel Glenn Hwy

Suite 300

Dayton OH 45431-1672

Data

Originator:

Leigh Taylor

Texas Instruments 2501 W. University

MS 8030

McKinney TX 75070 (214) 952-5239

Data

Description:

Technical Manual Test

Document Declaration filesDocument Type Definitions (DTD)

2 Text/Standard Generalzed Markup Language

(SGML) files

27 Computer Graphics Metafile (CGM) files

Data

Source System:

1840

HARDWARE

Sun Workstation

Hewlett Packard Tape Drive

SOFTWARE

Interleaf

Text/SGML

HARDWARE

Sun Workstation

SOFTWARE

Interleaf

CGM

HARDWARE

Sun Workstation

SOFTWARE

Interleaf

Evaluation Tools Used:

MIL-STD-1840A (TAPE)

SUN 3/280

AFCTN Tapetool v1.2.10 UNIX XSoft CAPS/CALS v40.4

MIL-M-28001 (SGML)

HP 735

SUN SparcStation 2

ArborText ADEPT v4.2.1

PC 486/50

Exoterica XGMLNormalizer v1.2e3.2 Exoterica Validator v2.0 exl McAfee & McAdam Sema Mark-it v2.3

MIL-D-28003 (CGM)

HP 735

InterCAP X-Change v7.82

SGI Indigo 2

IGES Data Analysis (IDA) CALSView

SUN SparcStation 2

ArborText cgm2draw
Carberry CADLeaf Plus v3.1
Island Software IslandDraw v3.0
Island Software IslandDraw v4.0

PC 486/50

Advanced Technology Center
(ATC) MetaCheck R 2.10
Software Publishing Corporation
(SPC) Harvard Graphics v3.05
Inset Systems HiJaak Pro
Lotus Freelance v2.01
Micrografx Designer v4.0
Corel Ventura Publisher

Standards Tested:

MIL-STD-1840A MIL-M-28001A MIL-D-28003

3. 1840A Analysis

3.1 External Packaging

The tape arrived at the Air Force CALS Test Bed (AFCTB) enclosed in a box in accordance with ASTM D 3951. The exterior of the box was marked with a magnetic tape warning label, as required by MIL-STD-1840A, para. 5.3.1.3.

The tape was enclosed in a barrier bag as required by MIL-STD-1840A, para. 5.3.1.2. Inspection of the tape reel showed the label indicating the recording density, as required by MIL-STD-1840A, para. 5.3.1. Enclosed in the box was a packing list showing all files recorded on the tape.

3.2 Transmission Envelope

The 9-track tape received by the AFCTB contained MIL-STD-1840A files. The files were named per the standard conventions.

3.2.1 Tape Formats

The tape was run through the AFCTN $Tapetool\ v1.2.10$ utility. No errors were encountered while evaluating the contents of the tape labels.

The tape was read using XSoft's CAPS read1840A utility without any reported errors in the media. Other errors were reported in the CALS headers and only one of the two documents was read off the tape.

The tapes physical structure meets the requirements defined in MIL-STD-1840A and ANSI x3.27.

3.2.2 Declaration and Header Fields

Sixty-seven errors and 110 notes were reported in the Document Declaration file and data file headers. Both document sets on the tape had similar errors.

The first error was missing data in the file count record. This record had no value indicating no data files. Both Tapetool and the XSoft tape utility reported this error.

filcnt:

- *** ERROR (MIL-STD-1840A; 5.1.1.2) Value missing after Document Declaration header field.
- *** NOTE The header record will be given the value NONE.
- *** NOTE Correction made in new Document Declaration Header File.

Because there was no value in the filcnt record, *Tapetool* assumed product data, then generated multiple errors and notes in the rest of the files.

txtfilid: W

- *** ERROR (MIL-STD-1840A; 5.1.4.1) Invalid 'txtfilid:' value for product data. Expected => NONE
- *** NOTE The header record will be given the value NONE.
- *** NOTE Correction made in new Text Header File.

The last type error was in the numbering of the files. The tape started with file D001T001, D001G001 and D001H001 followed by D001C001. The file numbers start with D001?001 and increment from there. The first CGM file should have been named D001C004.

Evaluating numbering scheme...

- *** ERROR (MIL-STD-1840A; 5.1.3) The data files for Document D001 were not numbered properly.
- *** NOTE (MIL-STD-1840A; 5.1.3) The first data file for a Document shall use "001" and the number shall increment sequentially for each file of the Document so that each file has a unique file name.

This portion of the tape does not meet the requirements defined in MIL-STD-1840A.

4. IGES Analysis

No Initial Graphics Exchange Specification (IGES) files were included in this evaluation.

5. SGML Analysis

The AFCTB has several parsers available for evaluating submitted DTD and text files. These tools are not used to generate a pass/fail but to report how commercially available software can handle the files. These products are used in the development of technical publications and are good indicators of usability. The use of these products is not an endorsement nor an indication of CALS capability. All operations were performed using the default settings unless specified in the report. Changes to DTD or text files required by each system are not documented in the report.

The tape contained two text files, two DTDs, and two Format Output Specification Instances (FOSIs). During the inspection of the files it was noted that the DTDs were MIL-M-38784C, Amendment C, which is the most current DTD. The text file contained the concrete syntax, the DTD listed above and the text file. It was necessary to break this file apart in order to use some of the parsers.

The text and DTD files were evaluated using the Exoterica Validator exl parser with no reported errors.

The text and DTD files were tested using the Exoterica XGMLNormalizer parser. No errors or warnings were reported in any of the SGML files.

The text and DTD files were evaluated using McAfee & McAdam's $Sema\ Mark-it\ v2.3$ parser. No errors or warnings were reported in any of the SGML files.

The text file was imported into ArborText's Adept software. File 9427-1 DTD parsed without a reported error. The included FOSI had an error that caused the system to report a segmentation fault. File set 9427-2 DTD and the FOSI parsed without a reported error. When importing the document into the publisher, an error was reported in the file with the "tfoot" and "thead" tags.

According to Chris Moffett of ArborText, Inc., "This (or These) warning(s) may be due to a syntax error in the DTD."

The DTD and text files parsed without a reported error through several commercial parsers. The FOSI in the first document set would not parse while the second document set parsed without a reported error. A problem occurred during an attempt to publish. The SGML files do not meet the CALS MIL-M-28001A specification.

6. Raster Analysis

No Raster files were included in this evaluation.

7. CGM Analysis

The tape contained 27 CGM files. The files were evaluated using ATC's *MetaCheck* with CALS options. Files D001C005, C013 and D002C001 reported basic CGM errors. These errors kept these files from meeting the CALS MIL-D-28003 specification.

The CGM files were evaluated using the beta AFCTN validcgm utility. This utility reported errors in all files. Note, this utility is a beta test and not used for pass/fail.

The AFCTB has several tools for viewing CGM files. These tools are not used to generate a pass/fail but to report how commercially available software can handle the files. Many of these products are used in the development of technical publications and are good indicators of usability. The use of these products is not an endorsement nor and indication of CALS capability. All operations were performed using the default settings.

All files were viewed using at least three difference software tools. Because of the number of files submitted, not all files were evaluated using all available tools. Files D001C004 (C104), D001C020 (C120), and D002C001 (C201) were selected for detailed inspection.

The CGM files were converted using ArborText's cgm2draw utility. File C201 had two degraded primitives reported.

The resulting files were read into Island Software's IslandDraw v3.1, displayed and printed. All files displayed errors. Typical of files generated using Interleaf CGM tools, some entities were flipped 180 degrees vertically. These circle and oval entities are displayed along the top of the image. A font change in file C120 resulted in a script font being used by some text.

According to Chris Moffett of ArborText, Inc. "This (or These) problem(s) may be due {to} the method in which the original file was generated."

All files were read into Carberry's *CADLeaf* software and displayed. No errors were reported during this process. The resulting images appeared to be correct with no noted errors.

The files were read into IDA's CALSView. File C201 had reported geometric errors. The other files displayed correctly.

The files were imported into Micrografx's Designer without a reported error. File C104 had missing lines. An oval entity was noted in the upper top of the paper. The light output is the result of the color. File C120 appeared to be complete. File C201 had several missing entities and was unusable.

According to Michael Harrison of Micrografx, Inc., "Micrografx is aware of the problems associated with reading these files and is working on a solution to be implemented in a future release of our products."

The files were imported into Lotus' Freelance and displayed with no reported errors in any of the three selected files.

The files were imported into SPC's Harvard Graphics v3.05 with a reported line style error for file C201. The files appear to be complete and correct with the exception of some minor distortion in file C201.

While trying to read the files into Inset Systems' HiJaak Pro, a real precision error was reported on all three files. Nothing displayed.

The files were imported directly into Island Software's IslandDraw v4.0 without a reported error. File C201 had some minor added lines noted.

The files were read into InterCAP's X-Change without a reported error. File C120 had the font changed in some text to script.

The files were imported into Corel's *Ventura Publisher* without a reported error with the exception of C201. This file would not import and an error was generated. The dotted lines in file C104 were displayed as solid.

Because of the reported errors in file C105, C113 and C201, the files do not meet the specification defined in MIL-D-28003.

8. Conclusions and Recommendations

The tape from Texas Instruments had errors in the CALS document declaration file. The filcnt record had no value. Additionally, the files were not numbered per the MIL-STD-1840A requirements. The physical tape structure does not meet the CALS MIL-STD-1840A requirements.

The SGML files parsed without a reported error using several commercial products. Document set one would not compile on the ArborText system because of errors in the FOSI. Using the included ArborText FOSI, Document Set two compiled, but it contained an error in the "tfoot" which kept it from being published. The first six pages were displayed correctly. The SGML files do not meet the MIL-M-28001A specification due to the problem with the FOSI.

Three of the 27 CGM files reported basic CGM errors. For this reason, the CGM files do not meet the CALS MIL-D-28003 specification.

The tape does not meet the CALS MIL-STD-1840A requirements, due to the errors in the SGML and CGM files, and the physical tape structure.

9. Appendix A - Tapetool Report Logs

9.1 Tape Catalog

CALS Test Network Catalog Evaluation - Version 1.2; Release 10 (C)

Standards referenced:

MIL-STD-1840A (1987) - Automated Interchange of Technical Information ANSI X3.27 (1987) - File Structure and labeling of Magnetic Tapes for Information Interchange ANSI X3.4 (1986) - Coded Character Sets - 7 Bit ASCII

Thu Apr 7 07:15:17 1994

MIL-STD-1840A File Catalog

File Set Directory: /cals/u1210/Set059

Page: 1

File Name	File Type	Record Format/ Length	Block Length/Total	Selected/ Extracted
D001 D001T001 D001G002 D001H003 D001C001	Document Declaration Text DTD Output Specification CGM	D/00260 D/00260 D/00260	02048/000001 02048/000071 02048/000016 02048/000043 00800/000005	Extracted Extracted Extracted Extracted Extracted
	<<<< PART OF LOG FIR	LE REMOVE	D HERE >>>>	
D001C022 D001C023 D002 D002T001 D002G002 D002H003 D002C001	CGM CGM Document Declaration Text DTD Output Specification CGM CGM	F/00080 D/00260 D/00260 D/00260 D/00260 F/00080	00800/000004 00800/000004 02048/000001 02048/000050 02048/000016 02048/000085 00800/000110 00800/000002	Extracted Extracted Extracted Extracted

Catalog Process terminated normally.

9.2 Tape Evaluation Log

```
CALS Test Network Tape Evaluation - Version 1.2; Release 10 (C)
  Standards referenced:
   ANSI X3.27 (1987) - File Structure and labeling of Magnetic Tapes
                        for Information Interchange
   ANSI X3.4 (1986) - Coded Character Sets - 7 Bit ASCII
Thu Apr 7 07:14:30 1994
```

ANSI Tape Import Log

Allocating tape drive /dev/rmt0...

/dev/rmt0 allocated.

VOL1CALS01

Label Identifier: VOL1 Volume Identifier: CALS01 Volume Accessibility: Owner Identifier:

Label Standard Version: 4

HDR1D001

CALS0100010001000100 94086 00000 0000001LEAF VER 1.7

Label Identifier: HDR1 File Identifier: D001 File Set Identifier: CALS01 File Section Number: 0001 File Sequence Number: 0001 Generation Number: 0001 Generation Version Number: 00

Creation Date: 94086 Expiration Date: 00000 File Accessibility:

Block Count: 000000

Implementation Identifier: ILEAF VER 1.7

<<<< PART OF LOG FILE REMOVED HERE >>>>

########### End of Volume CALS01 ############# ########### End Of Tape File Set ##############

Deallocating /dev/rmt0...

Tape Import Process terminated normally.

9.3 Tape File Set Validation Log

```
CALS Test Network File Set Evaluation - Version 1.2; Release 10 (C)
  Standards referenced:
    MIL-STD-1840A (1987) - Automated Interchange of Technical Information
Thu Apr 7 07:15:18 1994
MIL-STD-1840A File Set Evaluation Log
File Set: Set059
Found file: D001
Extracting Document Declaration Header Records...
Evaluating Document Declaration Header Records...
srcsys: Interleaf Inc., Waltham, Ma.
srcdocid: TM 9-XXXX-XXX-12
srcrelid: OPERATOR MAINTENANCE MANUAL
chglvl: ORIGINAL
dteisu: 19940328
dstsys: MICOM - ArborText
dstdocid: TM 9-XXXX-XXX-12
dstrelid: TBD
dtetrn: 19940228
dlvacc: ITAS; DAAH01-93-C-0206; A059
*** ERROR (MIL-STD-1840A; 5.1.1.2) - Value missing after Document Declaration
    header field.
*** NOTE - The header record will be given the value NONE.
*** NOTE - Correction made in new Document Declaration Header File.
ttlcls: Unclass
doccls: Unclass
doctyp: TECHNICAL MANUAL
docttl: OPERATOR AND ORGANIZATIONAL MAINTENANCE
1 error(s), 0 warning(s), and 2 note(s) were encountered
in Document Declaration File D001.
Found file: D001T001
Extracting Text Header Records...
Evaluating Text Header Records...
```

srcdocid: TM 9-XXXX-XXX-12 dstdocid: TM 9-XXXX-XXX-12 txtfilid: W *** ERROR (MIL-STD-1840A; 5.1.4.1) - Invalid 'txtfilid:' value for product data. Expected => NONE *** NOTE - The header record will be given the value NONE. *** NOTE - Correction made in new Text Header File. doccls: Unclass notes: ITAS Operator and Organizational Maintenance Manual; Texas Instruments 1 error(s), 0 warning(s), and 2 note(s) were encountered in Text File D001T001. Saving Text Header File: D001T001 HDR Saving Text Data File: D001T001_TXT Found file: D001G002 Extracting DTD Header Records... Evaluating DTD Header Records... srcdocid: TM 9-XXXX-XXX-12 dstdocid: TM 9-XXXX-XXX-12 notes: Interleaf DTD Saving DTD Header File: D001G002_HDR Saving DTD Data File: D001G002_DTD Found file: D001H003 Extracting Output Specification Header Records... Evaluating Output Specification Header Records... srcdocid: TM 9-XXXX-XXX-12 dstdocid: TM 9-XXXX-XXX-12 notes: FOSI Included with Interleaf. Saving Output Specification Header File: D001H003 HDR Saving Output Specification Data File: D001H003_OS Found file: D001C001 Extracting CGM Header Records... Evaluating CGM Header Records... srcdocid: TM 9-XXXX-XXX-12 dstdocid: TM 9-XXXX-XXX-12 txtfilid: W *** ERROR (MIL-STD-1840A; 5.1.4.5) - Invalid 'txtfilid:' value for product data. Expected => NONE

*** NOTE - The header record will be given the value NONE.

*** NOTE - Correction made in new CGM Header File.

figid: 01

srcgph: LAUNCHER

*** ERROR (MIL-STD-1840A; 5.1.4.5) - Invalid 'srcgph:' value for product data. Expected => NONE

*** NOTE - The header record will be given the value NONE.

*** NOTE - Correction made in new CGM Header File.

doccls: Unclass notes: Launch tube

2 error(s), 0 warning(s), and 4 note(s) were encountered
in CGM File D001C001.

Saving CGM Header File: D001C001_HDR Saving CGM Data File: D001C001_CGM

<<<< PART OF LOG FILE REMOVED HERE >>>>

Evaluating numbering scheme...

*** ERROR (MIL-STD-1840A; 5.1.3) - The data files for Document D001 were not numbered properly.

*** NOTE (MIL-STD-1840A; 5.1.3) - The first data file for a Document shall use "001" and the number shall increment sequentially for each file of the Document so that each file has a unique file name.

Renumbering data files...

Updating Map File for Document D001

*** NOTE - 3 file(s) were renumbered.

Numbering scheme evaluation complete.

Checking file count...

*** ERROR (MIL-STD-1840A; 5.1.1.2) - Actual CGM File Count does not match filent record. Actual => 23, Expected => 0.

*** ERROR (MIL-STD-1840A; 5.1.1.2) - Actual DTD File Count does not match filent record. Actual => 1, Expected => 0.

*** ERROR (MIL-STD-1840A; 5.1.1.2) - Actual Output Specification File Count does not match filent record. Actual => 1, Expected => 0.

*** ERROR (MIL-STD-1840A; 5.1.1.2) - Actual Text File Count does not match filent record. Actual => 1, Expected => 0.

*** NOTE - Correction made in new Document Declaration header file.

4 error(s) were encountered during file count verification. File Count verification complete.

A total of 57 error(s), 0 warning(s), and 98 note(s) were encountered in Document D001.

Found file: D002

Extracting Document Declaration Header Records...
Evaluating Document Declaration Header Records...

srcsys: Interleaf Inc., Waltham, Ma. srcdocid: TM 9-XXXX-XXX-30 srcrelid: PRELIMINARY DS MAINTENANCE chqlvl: ORIGINAL dteisu: 19940325 dstsys: MICOM - ArborText dstdocid: TM 9-XXXX-XXX-30 (soon to be -34) dstrelid: TBD dtetrn: 19910816 dlvacc: ITAS; DAAH01-93-C-0206; A059 filcnt: NONE ttlcls: Unclass doccls: Unclass doctyp: TECHNICAL MANUAL docttl: DIRECT SUPPORT MAINTENANCE MANUAL Found file: D002T001 Extracting Text Header Records... Evaluating Text Header Records... srcdocid: TM 9-XXXX-XXX-30 dstdocid: TM 9-XXXX-XXX-30 txtfilid: W *** ERROR (MIL-STD-1840A; 5.1.4.1) - Invalid 'txtfilid:' value for product data. Expected => NONE *** NOTE - The header record will be given the value NONE. *** NOTE - Correction made in new Text Header File. doccls: Unclass notes: This document will be combined with the -40 to make a -34 TM 1 error(s), 0 warning(s), and 2 note(s) were encountered in Text File D002T001. Saving Text Header File: D002T001_HDR Saving Text Data File: D002T001_TXT Found file: D002G002 Extracting DTD Header Records... Evaluating DTD Header Records...

Saving DTD Header File: D002G002_HDR Saving DTD Data File: D002G002_DTD

srcdocid: TM 9-XXXX-XXX-30
dstdocid: TM 9-XXXX-XXX-30
notes: Interleaf 38784C DTD

Found file: D002H003 Extracting Output Specification Header Records... Evaluating Output Specification Header Records... srcdocid: TM 9-XXXX-XXX-30 dstdocid: TM 9-XXXX-XXX-30 notes: ArborText FOSI, copied from 38784C-901012.fos, replaced contents of Interleaf FOSI Saving Output Specification Header File: D002H003_HDR Saving Output Specification Data File: D002H003 OS Found file: D002C001 Extracting CGM Header Records... Evaluating CGM Header Records... srcdocid: TM 9-XXXX-XXX-30 dstdocid: TM 9-XXXX-XXX-30 txtfilid: W *** ERROR (MIL-STD-1840A; 5.1.4.5) - Invalid 'txtfilid:' value for product data. Expected => NONE *** NOTE - The header record will be given the value NONE. *** NOTE - Correction made in new CGM Header File. figid: 01 srcgph: ITAS1 *** ERROR (MIL-STD-1840A; 5.1.4.5) - Invalid 'srcgph:' value for product data. Expected => NONE *** NOTE - The header record will be given the value NONE. *** NOTE - Correction made in new CGM Header File. doccls: Unclass notes: ITAS with Launch Tube & Tripod 2 error(s), 0 warning(s), and 4 note(s) were encountered in CGM File D002C001. Saving CGM Header File: D002C001 HDR Saving CGM Data File: D002C001_CGM

<<<<< PART OF LOG FILE REMOVED HERE >>>>

Evaluating numbering scheme...

*** ERROR (MIL-STD-1840A; 5.1.3) - The data files for Document D002 were not numbered properly.

*** NOTE (MIL-STD-1840A; 5.1.3) - The first data file for a Document shall use "001" and the number shall increment sequentially for each file of the Document so that each file has a unique file name.

Renumbering data files...

Updating Map File for Document D002

*** NOTE - 3 file(s) were renumbered. Numbering scheme evaluation complete.

Checking file count...

- *** ERROR (MIL-STD-1840A; 5.1.1.2) Actual CGM File Count does not match filent record. Actual => 2, Expected => 0.
- *** ERROR (MIL-STD-1840A; 5.1.1.2) Actual DTD File Count does not match filent record. Actual => 1, Expected => 0.
- *** ERROR (MIL-STD-1840A; 5.1.1.2) Actual Output Specification File Count does not match filent record. Actual => 1, Expected => 0.
- *** ERROR (MIL-STD-1840A; 5.1.1.2) Actual Text File Count does not match filent record. Actual => 1, Expected => 0.
- *** NOTE Correction made in new Document Declaration header file.
- 4 error(s) were encountered during file count verification. File Count verification complete.

A total of 10 error(s), 0 warning(s), and 12 note(s) were encountered in Document D002.

A grand total of 67 error(s), 0 warning(s), and 110 note(s) were encountered in this File Set.

MIL-STD-1840A File Set Evaluation Complete.

9.4 Other Tape Reading Logs

```
/cals/caps/Bin/read1840A: --- Read declaration file 'D001
/cals/caps/Bin/read1840A: writing data file '94027/TM9-XXXX-XXX-12/
W.T.sgm'.
/cals/caps/Bin/read1840A: writing data file '94027/TM9-XXXX-XXX-12/
TM9XXXXXXX12.G.dtd'.
/cals/caps/Bin/read1840A: writing data file '94027/TM9-XXXX-XXX-12/
TM9XXXXXXX12.H.out'.
/cals/caps/Bin/read1840A: writing data file '94027/TM9-XXXX-XXX-12/
LAUNCHER.C.cgm'.
/cals/caps/Bin/read1840A: writing data file '94027/TM9-XXXX-XXX-12/
MISSILE.C.cgm'.
/cals/caps/Bin/read1840A: writing data file '94027/TM9-XXXX-XXX-12/
TAS.C.cgm'.
/cals/caps/Bin/read1840A: writing data file '94027/TM9-XXXX-XXX-12/
FCS.C.cgm'.
/cals/caps/Bin/read1840A: writing data file '94027/TM9-XXXX-XXX-12/
TU.C.cgm'.
/cals/caps/Bin/read1840A: writing data file '94027/TM9-XXXX-XXX-12/
BPS.C.cgm'.
/cals/caps/Bin/read1840A: writing data file '94027/TM9-XXXX-XXX-12/
AIM.C.cgm'.
/cals/caps/Bin/read1840A: writing data file '94027/TM9-XXXX-XXX-12/
FIRE.C.cgm'.
/cals/caps/Bin/read1840A: writing data file '94027/TM9-XXXX-XXX-12/
GUIDE.C.cgm'.
/cals/caps/Bin/read1840A: writing data file '94027/TM9-XXXX-XXX-12/
CORRECT.C.cgm'.
/cals/caps/Bin/read1840A: writing data file '94027/TM9-XXXX-XXX-12/
IRDETECT.C.cgm'.
/cals/caps/Bin/read1840A: writing data file '94027/TM9-XXXX-XXX-12/
TRIPOD.C.cgm'.
/cals/caps/Bin/read1840A: writing data file '94027/TM9-XXXX-XXX-12/
TU.C.cgm'.
/cals/caps/Bin/read1840A: writing data file '94027/TM9-XXXX-XXX-12/
handgrip.C.cgm'.
/cals/caps/Bin/read1840A: writing data file '94027/TM9-XXXX-XXX-12/
FCSCONT.C.cgm'.
/cals/caps/Bin/read1840A: writing data file '94027/TM9-XXXX-XXX-12/
TAS1.C.cgm'.
/cals/caps/Bin/read1840A: writing data file '94027/TM9-XXXX-XXX-12/
BPS.C.cgm'.
/cals/caps/Bin/read1840A: writing data file '94027/TM9-XXXX-XXX-12/
decals.C.cgm'.
/cals/caps/Bin/read1840A: writing data file '94027/TM9-XXXX-XXX-12/
move.C.cgm'.
```

```
/cals/caps/Bin/read1840A: writing data file '94027/TM9-XXXX-XXX-12/
RANG1FT.C.cgm'.
/cals/caps/Bin/read1840A: writing data file '94027/TM9-XXXX-XXX-12/
RANG2FT.C.cgm'.
/cals/caps/Bin/read1840A: writing data file '94027/TM9-XXXX-XXX-12/
RANGIM.C.cqm'.
/cals/caps/Bin/read1840A: writing data file '94027/TM9-XXXX-XXX-12/
RANG2M.C.cqm'.
-- declaration file indicates 0 files of type T
-- declaration file indicates 0 files of type G
-- declaration file indicates 0 files of type H
-- declaration file indicates 0 files of type Q
-- declaration file indicates 0 files of type R
-- declaration file indicates 0 files of type C
-- declaration file indicates 0 files of type X
-- declaration file indicates 0 files of type P
-- declaration file indicates 0 files of type Z
*** WARNING: Declaration file indicates 0 SGML files, but tape contains 1 files.
*** WARNING: Declaration file indicates 0 DTD files, but tape contains 1 files.
*** WARNING: Declaration file indicates 0 Output Specification files, but tape
contains 1 files.
*** WARNING: Declaration file indicates 0 CGM files, but tape contains 23 files.
```

10. Appendix B - Detailed SGML Analysis

10.1 Parser Log

SGML Document Type Definition Parser
An SGML System Conforming to
International Standard ISO 8879
Standard Generalized Markup Language

Log file: '9427-1.LOG' SDO File: 'ctndecl.sdo' Namecase General is yes. Namecase Entity is no.

Parsing DTD file: '9427-1.dtd'

Parsing DOCTYPE DOC

DTD0096: The generic ID SHORTTITLE has not been used in any content model, inclusion, or as a doctype element.

This DTD conforms to the ISO 8879 standard

DTO file '9427-1.DTO' created

closing statistics:

Capacity points: 56072
Bytes of DTO file string space: 18083
SGML descriptor blocks: 5865

Document Type Definition is compliant and parsed normally.

Program status code: 0.

IPA0108: *** SGML Instance Parser Log File ***

Source Document File: '\xgml\9427-1.txt'.

Job File:

'9427-1.jbf'.

DTD File:

11

SGML Declaration File: ''.

Reading File '9427-1.jbf', File Type 'JOB FILE'.

Concrete Syntax Settings In Effect For This Parse:

NAMECASE GENERAL: YES.
NAMECASE ENTITY: NO.
NAMELEN: 32.
SHORTTAG: YES.

Closed '9427-1.jbf', File Type 'JOB FILE'.

Reading File '\xgml\9427-1.txt', File Type 'DIRECT INPUT FILE'.

```
--> Scanned Up To Line 100 In \xgml\9427-1.txt.
   --> Scanned Up To Line 200 In \xgml\9427-1.txt.
   --> Scanned Up To Line 300 In \xgml\9427-1.txt.
   --> Scanned Up To Line 400 In \xgml\9427-1.txt.
   --> Scanned Up To Line 500 In \xgml\9427-1.txt.
   --> Scanned Up To Line 600 In \xgml\9427-1.txt.
   --> Scanned Up To Line 700 In \xgml\9427-1.txt.
   --> Scanned Up To Line 800 In \xgml\9427-1.txt.
   --> Scanned Up To Line 900 In \xgml\9427-1.txt.
   --> Scanned Up To Line 1000 In \xgml\9427-1.txt.
   --> Scanned Up To Line 1100 In \xgml\9427-1.txt.
   --> Scanned Up To Line 1200 In \xgml\9427-1.txt.
  --> Scanned Up To Line 1300 In \xgml\9427-1.txt.
   --> Scanned Up To Line 1400 In \xqml\9427-1.txt.
   --> Scanned Up To Line 1500 In \xgml\9427-1.txt.
   --> Scanned Up To Line 1600 In \xgml\9427-1.txt.
   --> Scanned Up To Line 1700 In \xgml\9427-1.txt.
   --> Scanned Up To Line 1800 In \xgml\9427-1.txt.
   --> Scanned Up To Line 1900 In \xgml\9427-1.txt.
Closed '\xgml\9427-1.txt', File Type 'DIRECT INPUT FILE'.
Document Parsed Successfully, No Errors or Warnings.
```

10.2 Exotercia Validator

```
9427-1
<!-- **Warning**:
  An element with mixed content should permit data characters ("#PCDATA") in
  all parts of its content model.
  The element being declared is "ENTRY".
   supscrpt | extref | dataiden )+) | (warning?, caution?, note?) | (seqlist
<!-- **Warning** in "9427-1.txt", line 1:
  An element is not allowed in the document instance because it does not
  appear in any accessible content model or it is completely excluded.
  The element is "SHORTTITLE".
<!-- **Warning** in "9427-1.txt", line 1:
   There is no element with an IDREF or IDREFS attribute value equal to a
   specified ID value.
  The unreferenced ID attribute value is "APPB".
<!-- 3 warnings reported. -->
9427-2
<!-- **Warning**:
   An element with mixed content should permit data characters ("#PCDATA") in
   all parts of its content model.
   The element being declared is "ENTRY".
   supscrpt | extref | dataiden )+) | (warning?, caution?, note?) | (seqlist
-->
<!-- **Warning** in "9427-2.sgm", line 1:
  An element is not allowed in the document instance because it does not
   appear in any accessible content model or it is completely excluded.
   The element is "SHORTTITLE".
<!-- 2 warnings reported. -->
```

10.3 Exoterica XGMLNormalizer Parser

No reported errors or warnings.

10.4 Sema Mark-it Log

No reported errors or warnings.

11. Appendix C - Detailed CGM Analysis

11.1 File D001C004

11.1.1 Parser Log MetaCheck

```
MetaCheck Version 2.05 -- CGM/MIL-D-28003 Conformance Analyzer
Copyright 1988-91 CGM Technology Software
Execution Date: 04/16/94
                          Time: 13:25:13
Metafile Examined : i:\94027\c104.cgm
Pictures Examined : All
Elements Examined : All
       Examined : All
Bytes
Tracing not selected.
======== CGM Conformance Violation Report =========
No Errors Detected
======= CALS CGM Profile (MIL-D-28003) Report =========
No profile discrepancies detected.
========== Conformance Summary Report ============
MetaCheck Version 2.05 -- CGM/MIL-D-28003 Conformance Analyzer
Copyright 1988-91 CGM Technology Software
                        Time: 13:25:14
Execution Date: 04/16/94
Name of CGM under test: i:\94027\c104.cgm
                   : Binary
Encoding
                 : All
Pictures Examined
Elements Examined
                 : All
        Examined
                  : All
Bytes
BEGIN METAFILE string: "Version 5.42, FCS_cgm.sty, 03/28/94 11:03:59"
METAFILE DESCRIPTION : "Interleaf Inc. MDL/G CGM 1992 ***
                      MIL-D-28003/BASIC-1"
```

```
Picture 1 starts at octet offset 394; string contains: "FCS"
```

Conformance Summary : This file conforms to the CGM specification.

This file meets the CALS CGM Profile (MIL-D-28003).

Summary of Testing Performed and Errors Found:

1 Pictures Tested 1859 Elements Tested 25756 Octets Tested

```
No Errors Were Detected
```


======== End of Conformance Report ===========

11.1.2 validcgm Log


```
Analysis for file c104.cgm using table table
ERROR: invalid times used per CGM (2), std B
ERROR: invalid times used per Picture (2), std B
                (1, 12, 12)
(14, 262)
                               Metafile Defaults Replacement
ERROR: illegal in this state (2), std B
ERROR: required precursor (0, 3) not yet seen
                              VDC Extent (0, 0) (32767, 32767)
                 (2, 6, 8)
(14.1, 0)
ERROR: invalid times used per CGM (3), std B
ERROR: invalid times used per Picture (3), std B
                                Metafile Defaults Replacement
                 (1, 12, 6)
ERROR: illegal in this state (2), std B
ERROR: required precursor (0, 4) not yet seen
                (5, 11, 2)
                                Text Precision Stroke
(15.1, 0)
(0, 1) occurred 1 time
(0, 2) occurred 1 time
(0, 3) occurred 1 time
(0, 4) occurred 1 time
(0, 5) occurred 1 time
(1, 1) occurred 1 time
(1, 2) occurred 1 time
(1, 3) occurred 1 time
(1, 4) occurred 1 time
(1, 5) occurred 1 time
(1, 6) occurred 1 time
(1, 7) occurred 1 time
(1, 8) occurred 1 time
(1, 9) occurred 1 time
```

- (1, 10) occurred 1 time (1, 11) occurred 1 time (1, 12) occurred 3 times
- (1, 12) occurred illegally 2 times
- (1, 13) occurred 1 time
- (1, 15) occurred 1 time
- (2, 1) occurred 1 time
- (2, 2) occurred 1 time
- (2, 3) occurred 1 time
- (2, 4) occurred 1 time
- (2, 5) occurred 1 time
- (2, 6) occurred 2 times
- (2, 6) occurred illegally 1 time
- (2, 7) occurred 1 time
- (3, 1) occurred 1 time
- (4, 1) occurred 1476 times
- (4, 4) occurred 25 times
- (4, 7) occurred 8 times
- (4, 17) occurred 81 times
- (4, 18) occurred 217 times
- (5, 2) occurred 4 times
- (5, 3) occurred 2 times
- (5, 4) occurred 1 time
- (5, 11) occurred 1 time
- (5, 11) occurred illegally 1 time
- (5, 14) occurred 1 time
- (5, 15) occurred 3 times
- (5, 16) occurred 3 times
- (5, 18) occurred 1 time
- (5, 23) occurred 3 times
- (5, 28) occurred 1 time
- (5, 29) occurred 1 time
- (5, 30) occurred 3 times
- (5, 34) occurred 1 time

11.1.3 Output CADLeaf




11.1.4 Output cgm2draw/IslandDraw



11.1.5 Output Designer

0




Designer 4.0

c104


11.1.6 Output Freelance

Freelance-C104




11.1.7 Output Harvard Graphics

HG305 C104




11.1.8 Output IslandDraw v4.0




ID4 C104

11.1.9 Output Ventura Publisher



11.1.10 Output X-Change



11.2 File D001C020

11.2.1 Parser Log MetaCheck

MetaCheck Version 2.05 -- CGM/MIL-D-28003 Conformance Analyzer Copyright 1988-91 CGM Technology Software Execution Date: 04/16/94 Time: 13:25:30 Metafile Examined : i:\94027\c120.cgm Pictures Examined : All Elements Examined : All Examined : All Tracing not selected. ======== CGM Conformance Violation Report ========== No Errors Detected ======= CALS CGM Profile (MIL-D-28003) Report ========= No profile discrepancies detected. ========== Conformance Summary Report ============ MetaCheck Version 2.05 -- CGM/MIL-D-28003 Conformance Analyzer Copyright 1988-91 CGM Technology Software Execution Date: 04/16/94 Time: 13:25:31 Name of CGM under test: i:\94027\c120.cgm : Binary Encoding Pictures Examined : All Elements Examined : All Bytes Examined : All BEGIN METAFILE string: "Version 5.42, RANG1FT_cgm.sty, 03/28/94 11:02:32" METAFILE DESCRIPTION : "Interleaf Inc. MDL/G CGM 1992 ***

MIL-D-28003/BASIC-1"

Picture 1 starts at octet offset 398; string contains: "RANG1FT"

Conformance Summary : This file conforms to the CGM specification.

This file meets the CALS CGM Profile (MIL-D-28003).

Summary of Testing Performed and Errors Found:

1 Pictures Tested 162 Elements Tested 2416 Octets Tested

No Errors Were Detected

========= End of Conformance Report ============

11.2.2 validcgm Log


Analysis for file c120.cgm using table table ERROR: invalid times used per CGM (2), std B ERROR: invalid times used per Picture (2), std B Metafile Defaults Replacement (1, 12, 12)ERROR: illegal in this state (2), std B ERROR: required precursor (0, 3) not yet seen VDC Extent (0, 0) (32767, 32767) (14.1, 0)(2, 6, 8)ERROR: invalid times used per CGM (3), std B ERROR: invalid times used per Picture (3), std B (1, 12, 6)Metafile Defaults Replacement (15, 282)ERROR: illegal in this state (2), std B ERROR: required precursor (0, 4) not yet seen Text Precision Stroke (5, 11, 2) (15.1, 0)(0, 1) occurred 1 time (0, 2) occurred 1 time (0, 3) occurred 1 time (0, 4) occurred 1 time (0, 5) occurred 1 time (1, 1) occurred 1 time (1. 2) occurred 1 time (1, 3) occurred 1 time (1, 4) occurred 1 time (1, 5) occurred 1 time (1, 6) occurred 1 time (1, 7) occurred 1 time (1, 8) occurred 1 time (1, 9) occurred 1 time (1, 10) occurred 1 time (1, 11) occurred 1 time

(5, 15) occurred 1 time


(1, 12) occurred 3 times (1, 12) occurred illegally 2 times (1, 13) occurred 1 time (1, 15) occurred 1 time (2, 1) occurred 1 time (2, 2) occurred 1 time (2, 3) occurred 1 time (2, 4) occurred 1 time (2, 5) occurred 1 time (2, 6) occurred 2 times (2, 6) occurred illegally 1 time (2, 7) occurred 1 time (3, 1) occurred 1 time (4, 1) occurred 67 times (4, 4) occurred 53 times (5, 3) occurred 5 times (5, 4) occurred 1 time (5, 10) occurred 3 times (5, 11) occurred 1 time (5, 11) occurred illegally 1 time (5, 14) occurred 1 time

(5, 16) occurred 1 time (5, 18) occurred 1 time (5, 34) occurred 1 time


11.2.3 Output CADLeaf



11.2.4 Output cgm2draw/IslandDraw




11.2.5 Output Designer




11.2.6 Output Freelance






11.2.7 Output Harvard Graphics


HG305 C120




11.2.8 Output IslandDraw v4.0



11.2.9 Output X-Change



11.2.10 Output Ventura Publisher



11.3 File D002C001

11.3.1 Parser Log MetaCheck

MetaCheck Version 2.05 -- CGM/MIL-D-28003 Conformance Analyzer Copyright 1988-91 CGM Technology Software

Execution Date: 04/16/94 Time: 13:25:33

Metafile Examined : i:\94027\c201.cgm

Pictures Examined : All Elements Examined : All Bytes Examined : All

Tracing not selected.

======== CGM Conformance Violation Report =========

Bulletin 2001: Element Class/ID: 4/7 Offset: 43038 octets Element No. 3443 Insufficient parameter data for this element.

Bulletin 2001: Element Class/ID: 4/7 Offset: 43258 octets Element No. 3460 Insufficient parameter data for this element.

Bulletin 2001: Element Class/ID: 4/7 Offset: 43506 octets Element No. 3478 Insufficient parameter data for this element.

Error 6076: Element Class/ID: 4/18 Offset: 43722 octets Element No. 3492 The three specifying points of the ELLIPTICAL ARC element are invalid; they must be distinct points.

Bulletin 20012: Element Class/ID: 4/13 Offset: 44694 octets Element No. 3546 Warning; CIRCULAR ARC 3 POINT with coincident/collinear points.

Error 6076: Element Class/ID: 4/18 Offset: 70224 octets Element No. 5244 The three specifying points of the ELLIPTICAL ARC element are invalid; they must be distinct points.

Error 6076: Element Class/ID: 4/18 Offset: 80688 octets Element No. 5827 The three specifying points of the ELLIPTICAL ARC element are invalid; they must be distinct points.

Bulletin 20012: Element Class/ID: 4/13 Offset: 82852 octets Element No. 5967 Warning; CIRCULAR ARC 3 POINT with coincident/collinear points.

Error 6076: Element Class/ID: 4/18 Offset: 85306 octets Element No. 6139 The three specifying points of the ELLIPTICAL ARC element are invalid; they must be distinct points.

======= CALS CGM Profile (MIL-D-28003) Report =========

No profile discrepancies detected.

========= Conformance Summary Report ===========

MetaCheck Version 2.05 -- CGM/MIL-D-28003 Conformance Analyzer

Copyright 1988-91 CGM Technology Software Execution Date: 04/16/94 Time: 13:25:36

Name of CGM under test: i:\94027\c201.cgm

Encoding : Binary

Pictures Examined : All Elements Examined : All Bytes Examined : All

BEGIN METAFILE string: "Version 5.42, ITAS1 cgm.sty, 03/25/94 10:00:10"

METAFILE DESCRIPTION : "Interleaf Inc. MDL/G CGM 1992 ***

MIL-D-28003/BASIC-1"

Picture 1 starts at octet offset 396; string contains: "ITAS1"

Conformance Summary : This file is not a conforming CGM.

Consequently, it does not meet the CALS CGM Profile (MIL-D-28003).

Summary of Testing Performed and Errors Found:

1 Pictures Tested 6233 Elements Tested 86726 Octets Tested

0 Il	legal CGM Elements	1000	-	1999
3 Inc	correct CGM Element Lengths	2000	-	2999
0 CGI	M State Errors	3000	-	3499
0 Red	quired CGM Elements Missing or Wrong	4000	-	4499
4 CGI	M Parameter Values Out of Range	6000	-	6499
0 CGI	M Structure Errors	7000	-	7499
7	*** CGM Errors Found (total)	***		

0 Profile State Errors 3500 - 3999 0 Illegal Profile Elements 4500 - 4999 0 Profile Parameter Values Out of Range 6500 - 6999

```
0 Profile Data Limits Exceeded 8500 - 8999
0 Other Profile Constraints Violated 9500 - 9999
0 *** Profile Violations Found (total) ***


2 Warnings (Advisory Remarks) 20000 - 20999
3 distinct errors and warnings were reported.
```

11.3.2 validcgm Log


```
Analysis for file c201.cgm using table table
ERROR: invalid times used per CGM (2), std B
ERROR: invalid times used per Picture (2), std B
                              Metafile Defaults Replacement
                (1, 12, 12)
ERROR: illegal in this state (2), std B
ERROR: required precursor (0, 3) not yet seen
                                VDC Extent (0, 0) (32767, 32767)
(14.1, 0)
                 (2, 6, 8)
ERROR: invalid times used per CGM (3), std B
ERROR: invalid times used per Picture (3), std B
                                Metafile Defaults Replacement
                (1, 12, 6)
(15, 280)
ERROR: illegal in this state (2), std B
ERROR: required precursor (0, 4) not yet seen
                               Text Precision Stroke
                 (5, 11, 2)
(0, 1) occurred 1 time
(0, 2) occurred 1 time
(0, 3) occurred 1 time
(0, 4) occurred 1 time
(0, 5) occurred 1 time
(1, 1) occurred 1 time
(1, 2) occurred 1 time
(1, 3) occurred 1 time
(1, 4) occurred 1 time
(1, 5) occurred 1 time
(1, 6) occurred 1 time
(1, 7) occurred 1 time
(1, 8) occurred 1 time
(1, 9) occurred 1 time
(1, 10) occurred 1 time
(1, 11) occurred 1 time
(1, 12) occurred 3 times
(1, 12) occurred illegally 2 times
(1, 13) occurred 1 time
(1, 15) occurred 1 time
(2, 1) occurred 1 time
```


- (2, 2) occurred 1 time
- (2, 3) occurred 1 time
- (2, 4) occurred 1 time
- (2, 5) occurred 1 time
- (2, 6) occurred 2 times
- (2, 6) occurred illegally 1 time
- (2, 7) occurred 1 time
- (3, 1) occurred 1 time
- (4, 1) occurred 5102 times
- (4, 4) occurred 14 times
- (4, 7) occurred 46 times
- (4, 12) occurred 4 times
- (4, 13) occurred 45 times
- (4, 17) occurred 68 times
- (4, 18) occurred 893 times
- (5, 3) occurred 1 time
- (5, 4) occurred 1 time
- (5, 11) occurred 1 time
- (5, 11) occurred illegally 1 time
- (5, 14) occurred 1 time
- (5, 15) occurred 2 times
- (5, 16) occurred 2 times
- (5, 18) occurred 1 time
- (5, 23) occurred 11 times
- (5, 28) occurred 1 time
- (5, 29) occurred 1 time
- (5, 30) occurred 11 times
- (5, 34) occurred 1 time

11.3.3 Output CADLeaf




11.3.4 Output cgm2draw/IslandDraw






11.3.6 Output Freelance



11.3.7 Output Harvard Graphics

HG305 C201



11.3.8 Output IslandDraw v4.0

